

QUESTION	ANSWER	TALLY
Site Considerations		
<i>Overall</i>	Poor traffic flow during drop-off/pick-up	23
	Electric vehicle staff parking	
	Parking space for athletics	
	Staff parking too narrow	
	Improve drainage on youth soccer fields	
	Visually appealing grounds; outdoor spaces	
	Improved outdoor lighting	2
	Repair curbs on Daley Street	
	Convert green space into parking or new roads	
<i>High School</i>	Roof drains onto staff parking (ice issues)	2
	Outdoor fitness equipment	
	Sidewalk to visitor team bleachers	
	Gate onto football field for vehicle access	
<i>Middle School</i>	Back receiving area often cluttered	
	Update furnishing in District Office	
	Sidewalk near art room drainage issues (ice)	
	Add outdoor seating under large tree	
<i>Elementary School</i>	Pickup area traffic flow	11
	Additional entrance & exit needed	2
	Natural outdoor play area	
	Fence in playground area	
	Parking lot needs resurfacing	2
<i>Early Learning Center</i>	Brighter exterior lighting	
	Specialized/special needs playground equipment	2
	Updated landscaping	
	Fence around playground for safety	5
	Cover/roof over sandbox	2
	Sidewalk drainage issues (ice)	2
	Lower swings on playground	2
	Thicker bed of wood chips on playground	2
	Limited staff parking space	
General Classroom Considerations		
<i>Overall</i>	Update intercom system district wide	
	More classrooms to lower student:teacher ratio	3
	All student/staff occupied spaces should have natural light	5
	Additional outlets in classrooms	14
	Update classrooms and facilities at MS and HS	8
	Wearable microphone systems for classrooms	
	Update clocks	
	Temperature/climate control is noisy	
	Update science rooms	
	Update bookshelves/cabinets/cupboards in all classrooms	3
<i>High School</i>	Non-operational outlets	
	Some classrooms undersized for class sizes	3
	Collaborative, adaptable furniture for group work	3

<i>Middle School</i>	HVAC system is difficult to control	4
	Classrooms use different keys, security concern	2
	Collaboration space in classrooms	2
	Curtains not adequate for classroom separation	5
<i>Elementary School</i>	Individual thermostats in classrooms/offices	2
	Some classrooms undersized for class sizes	2
	Lighting flexibility	4
<i>Early Learning Center</i>	HVAC system is difficult to control	
	Poor Wi-Fi connection/speed	2
	Carpeted spaces in classrooms	2
	Restrooms in each classroom would be ideal	
Specialty Space Considerations (art, music, etc.)		
<i>Overall</i>	Auditorium for district-wide use	5
	Mindfulness/calm down spaces	6
	Adequate storage for equipment/instruments/risers/shells.	
	Update band and choir rooms	
	One area for all 3 technology education programs. Combine wood shop, welding, and auto into one area/space/building with current updates	3
	More natural light	8
<i>High School</i>	New seating in "Little Theater"	
	Larger theater/performance space	5
	Welding shop requires stationary computers	
	Single level music rooms are ideal	2
	Main Office congested, security issues	
	Music rooms are undersized, lacking acoustics	5
	Redesign Special Education classrooms	2
	Art room clay area floor treatment to prevent slipping	
	Ovens and dishwasher in food science classroom	
	Sound proof practice rooms	
	Update equipment in Tech Ed areas, CNC, robotics	
	More floor space that allowa for indoor framing, masonry, drywall, plumbing, electrical, etc.	
	Overhead doors in this area to access larger equipment and building projects.	
<i>Middle School</i>	Bleachers in need of replacement	2
	Lighting in gym corners not sufficient	
	More evenly distributed Special Education classrooms	
	Update woodshop air exchanges.	
<i>Elementary School</i>	Remove "Story Pit" in library	2
	General improvements in Library (furniture, space, lighting)	3
	Additional manual sinks in art room	
	Kitchen is undersized	
<i>Early Learning Center</i>	Inadequate space in shared Library space	
	Designated spaces for Art, Music, Library, STEM, etc.	5

Storage Requirements		
<i>Overall</i>	Additional storage closets in classrooms	
<i>High School</i>	Inadequate storage for instruments, band uniforms	3
	Locking cabinets for Chromebooks	2
	PE department struggles to find appropriate space	3
<i>Middle School</i>	Unused lockers currently being use for storage	
	Cabinets in classroom spaces similar to elementary	
<i>Elementary School</i>	Library requires more storage for supplies/personal items	2
<i>Early Learning Center</i>	Storage shed for outdoor toys needed	
	Classrooms not large enough for toy/supply storage	
	Sharing closets not ideal for 4K classrooms	
	Shelving in storage closets is in poor condition	
Hazards or Concerns		
<i>High School</i>	Clutter in hallways and circulation spaces	
	Tripping hazards from instruments in Music rooms	2
	Exposed electrical in Art room	
	Sagging ceiling tiles (roof leaks)	
	Excessive amounts of exits/doors	
	Inadequate supervision of weight room	
	Pottery kiln in same space as students	2
	Music area is only accessible by stairs	2
	Boiler goes out frequently in winter	
<i>Middle School</i>	Inadequate ventilation and humidity control	4
	Lack of accessible and inclusive restrooms	2
	No PA speaker in some classrooms	3
	Falling light covers	
	Entrance is not secure	2
<i>Elementary School</i>	Library area lacks tornado safety space	
	Entrance is not secure	
	Large glass windows, security concern	
	Steps in "Story Pit" trip hazard	
	Peeling carpet create trip hazards	
	Chemicals and garbage kept in food service areas	2
	Boiler room leaks into food storage	
	Too few restrooms for students and staff	
	Rodent issues	
	Uneven floors in physical therapy room	
	Falling ceiling tiles	2
	No PA speaker in some classrooms	
<i>Early Learning Center</i>	Periodic air quality/ventilation issues	3
	Slippery floors during winter months	2
	Entrance not located near main office, security issue	

Innovations to Better Use Space		
<i>Overall</i>	Inconsistent entrance locks and keys	
	Full classrooms being used as storage is inefficient	
	Movable furniture and storage for use customization	2
<i>High School</i>	Better utilization of old locker rooms	
	Music department at maximum capacity within footprint	
	Library spaces and computer labs reconfiguration	
	Move aquaculture system to greenhouse, repair outlets	
	Infill courtyard for learning space	
<i>Middle School</i>	Science rooms in need of reconfiguration	
<i>Elementary School</i>	Better usage of space in staff workroom	2
<i>Early Learning Center</i>	Close building in Plain (consolidate in Spring Green)	
	More usable counter space in existing classrooms	
	Small group instruction rooms	3
Space Needs		
<i>Overall</i>	Commons area in all buildings	
	Additional classrooms to reduce crowding	2
	Performing arts center / auditorium	19
	Additional storage for classrooms	5
	Conference rooms at each building	
	Space for nursing staff and supplies at each building	
	Collaborative areas for small group work	5
	Furniture for breakout spaces	
<i>High School</i>	Gymnastics practice space	5
	Larger welding shop with metals storage	2
	Space for specialty storage items	3
	AG - large animal facility and office	
	Auxiliary gym for batting cages	
<i>Middle School</i>	Replace Middle School building for more space	3
	Central commons space	
	Collaboration and small group spaces	9
	Outdoor learning spaces	2
	Larger staff lounge	2
	Larger middle school gym	2
	Art kiln room needed, update flooring and ventilation	
	Fitness room with exercise equipment	
<i>Elementary School</i>	Tech/STEM space with lab	2
	Restroom in 5/6 hallway	
	Separate cafeteria and gym space	7
	Mental health / quiet room	4
	Additional kitchen space and food storage	2
	Collaboration and small group spaces	2
	OT/PT spaces inadequate	
	Additional special education classrooms with bathrooms	
	additional office space for service providers (ELL, Audiology, Braille, Therapy, etc.)	2
	Additional gymnasium	3
<i>Early Learning Center</i>	Dedicated music room	
	Additional storage	4

	Larger Speech and Language spaces	
	Dedicated art room	2
	Additional staff restrooms	
	Storage space for PE, specialty items	2
Circulation		
	<i>High School</i> Congestion in "Center Court" area	
	Lockers in hallways clog movement	
	Music area difficult to find and access with stairs	
	Separate parking area from bus lane	
	HS students walk to middle school for woods classes	
	<i>Middle School</i> Poorly designed circulation	3
	Younger students mix too much with oldest students	
	Narrow hallways	2
	<i>Elementary School</i> Lack of lockers for students clutters hallway with items	
	<i>Early Learning Center</i> Overcrowded restrooms creates bottlenecks	2
Disruptions Encountered		
	<i>Overall</i> Wi-Fi outages disrupt classes	2
	Inconsistent heating and cooling creates distractions	4
	<i>High School</i> Deliveries and commotion outside classroom windows	
	Noise from air handlers	2
	Improper moisture control creating mold	
	Disruption between ensembles in music area	
	<i>Middle School</i> Intervention spaces are not sound protected, distracting	4
	Inconsistent heating and cooling create in comfort	2
	Noise from gym and music in district offices	2
	Maintenance on roof is distracting	
	Doors slam loudly when closed	
	<i>Elementary School</i> Hallway noise	
	Lack of ventilation in art room traps odors	
	Sound travels through walls easily	2
	<i>Early Learning Center</i> Special education classrooms near library and music	
	Too few restrooms results in issues	

Other Comments		
<i>Overall</i>	Consolidate all spaces into new building	2
	Create "pods" for grade levels in all schools	
	Indoor track	2
	Indoor pool	3
<i>High School</i>	Consolidate athletic awards to athletic wing	
	Green and maroon lockers/tack boards unsightly	
	Low quality music spaces, lack of performing arts center	
	Soundproofing of counseling offices	
	Update staff workroom	
<i>Middle School</i>	Lockers are in poor condition	7
	Utilize as performing arts center	
	Updated kitchen equipment at middle school	
<i>Elementary School</i>	Additional staff restrooms	
	Brighter lighting and interior finishes	
	Staff sink is difficult to wash dishes in	3
	More natural light (windows)	3
<i>Early Learning Center</i>	Welcoming signs/artwork/graphics	
	Lack of windows/natural light is depressing	
	Improved signage for offices and classrooms	